Internal 007/019 CC: Pete

Michael O. Leavitt Kathleen Clarke Executive Director Lowell P. Braxton

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) Division Director 801-538-7223 (TDD)

August 21, 2000

TO:

Internal File

THRU:

Daron R. Haddock, Permit Supervisor

FROM:

James D. Smith, Senior Reclamation Specialist 505

RE:

1999 Fourth Quarter Water Monitoring, Andalex Resources, Inc., Centennial

Project, ACT/007/019-WQ99-4

1. Were data submitted for all of the MRP required sites?

YES[]

NO [X]

Identify sites not monitored and reason why, if known:

No flow at sites 7-1, 8-1, 17-1, 17-2, S18-1, 18-2, 18-3, 18-4, and 25-2; negligible flow at S25-1; and no report at all for 12-1 (Alrad Cyn).

2. On what date does the MRP require a five-year resampling of baseline water data.

See Technical Directive 004 for baseline resampling requirements. Consider the fiveyear baseline resubmittal when responding to question one above. Indicate if the MRP does not have such a requirement.

Resampling Due Date

During the year preceding each repermitting action: one sample for baseline analysis at high and one at low flow for surface-monitoring sites, and one at low flow for ground-water monitoring sites. Next renewal submittal due 09/04/01, for renewal on 04/04/02.

3. Were all required parameters reported for each site?

YES[X]

NO[]

Comments, including identity of monitoring site:

4. Were irregularities found in the data?

YES[X] NO[]

Comments, including identity of monitoring site:

Dissolved iron (4.9 mg/L or 4,900 μ g/L) is at least 10 times greater than the previous high $(320~\mu g/L)$ and well outside two standard deviations from the mean value recorded in the APPX